



FIG. 1 (PRIOR ART)












FIG. 3












FIG. 7A




FIG. /3




FIG. 8A




FIG. 88








FIG. 80












FIG. 11A




FIG. :18





FIG. 12



8-bit syndrome code	32-bit correction code
0x07	0x00000001
0x0e	0x00000002
0x1c	0x00000004
0x38	0x00000008
0x70	0x00000010
0xe0	0x00000020
0xc7	0x00000040
0x89	0x00000080
0x15	0x0000100
0x2a	0x00000200
0x54	0x00000400
0xa8	0x00000800
0x57	0×00001000
0xae	0×00002000
0x5b	0×00004000
0xb6	0×00008000
0x6b	0x00010000
0xd6	0x00020000
0xab	0x00040000
0x51	0x00080000
0xa2	0x00100000
0x43	0x00200000
0x86	0x00400000
0x0b	0x00800000
0x16	0x01000000
0x2c	0x02000000
0x58	0x04000000
0xb0	0x08000000
0x67	0×10000000
0xce	0×20000000
0x9b	0×4000000
0x31	0×80000000
default	0×00000000

FIG. 14




FIG. 15